

Spanwise Beam 3 - Lower chord
& web segment, RBL 73 to
RBL 107

CW634

Id No: 9-21-96-1

Tag No. Z-2863 Green

This segment is the vertical flange (flange common to web) of the lower chord and web. The web is attached to the chord segment with approx 95% of the fasteners intact. Six fasteners were fractured at web & chord interface. Remaining fasteners missing or sheared. Web portion conform to the size and shape of the chord segment. Part is sooted.

D James
2/3/97

Spanwise Beam 3 - Lower chord
& web segment, RBL 53 to
RBL 73

CW635

Id No: 11-11-96-27

Tag No: Z-4021 Green

This segment is the vertical lower chord flange (flange common to the web) and a portion of the horizontal flange of the lower chord. The web portion of the segment conforms in size and shape the vertical flange of the chord. All fastener common to chord & web are intact, except for 2 missing fasteners. Inbd & outbd edges of chord fractured at fastener locations. All fasteners common to horiz flange are sheared or missing. Part is sooted.

D James
2/3/97

Mark V. Tol
16/17 ALPS

Dennis Santiago IAM
4-2-97

B. Anderson - ISA 3/24/97

15/17 ALPS
16/17 ALPS