


CW636

Id No: 11/8/96-11

Tag No: Z-4023 Green

Spanwise Beam 3- Web segment,
Near lower chord, RBL 98.6

Part is extensively distorted and sooted. Segment is also shows signs of salt water corrosion. A more accurate description of part is difficult due to distortion of part. See attached map for probable undistorted size and shape.



Veigh D Johnson - ALFA
3-21-97

Dennis Santiago JRM
4-2-97

Shandishudun
TWA 3/24/97

Stephen F. Kaprielian
FAA-CA-62-97