

Spanwise Beam 3 - Stiffener
Segment, RBL 11.31

CW641
Id No: 11/16/96-206
Tag No: X-4071 Red

Segment is \approx 13 inches in length. Segment includes the free flange of the stiffener and approx 80% of the flange perpendicular to the free flange. Segment shows signs of salt water corrosion. No sooting was noted

ALPA
3-21-97

Stephen F. Kligman H30
FAA - CA - 03-97

D James
2/4/97

Demis Santiago IAM
4-2-97

Bwanderhuden TWA 3/24/97

Spanwise Beam 3 - Stiffener
& web segment, RBL 11.31

CW642
Id No: 11/17/96-140
Tag No: X-4019 Red

Segment is approx 7" wide by 10" tall. Segment includes an approx 7" wide by 6" tall web portion, and 10" tall stiffener segment. The stiffener segment includes the flange common to the web and flange perpendicular. Part shows signs of salt water corrosion. No sooting was noted.

ALPA
3-21-97

Bwanderhuden
TWA 3/24/97

Demis Santiago IAM
4-2-97

Stephen F. Kligman H30
FAA - CA - 03-97

D James
2/4/97