



Structures 7 - Exhibit No. 7C - Photo 10. View of the damage to the forward fuselage, left side and crown. Note the approach lighting system structural support platform, entangled with the torn away airframe