



Structures 7 - Exhibit No. 7C - Photo 13. View of the rear fuselage and right wing. Note the passenger cabin and upper fuselage consumed by fire. Note the detached landing gear and inboard section of the inboard flap immediately aft of the wing..