



Structures 7 - Exhibit No. 7C - Photo 4. Aerial photo of N215AA wreckage. Note the separation of the fuselage and left wing. Note the structural damage to the forward fuselage and fire damage to the rear fuselage. (Photo by J.K. Lloyd's, Inc.)