



Structures 7 - Exhibit No. 7C - Photo 5. Aerial photo. Note the orientation of the forward fuselage in relation to the rest of the airplane. Note the structural support column at the aft galley service door. (Photo by J.K. Lloyd's Inc.)