



Structures 7 - Exhibit No. 7C - Photo 7. View of the left wing separation near its root. Note the displacement of the forward fuselage from the remainder of the airplane and fire damage to the rear fuselage. View looking South. (NTSB))