



Structures 7 - Exhibit No. 7C - Photo 8. View of the cockpit. Note the complete destruction of the nose section, left side, and flooring. Note the lighting system structure entangled with the fuselage and the entrance door found ajar.