		[93]
	•• .	
B B	Section of the section	
	D	

## GREEN DEBRIS FIELD

LOG# L	F-41 P-3
TARGET#	
COORD: LAT _	5
LONG	?
_	

DEBRIS FIELD GREEN

THIS SECTION ENCOMPASSES AN AREA WHICH INCLUDES STATION 1920 BACK TO STA. 2020. AND INCLUDES A JAGGERED PATTERN OF TORN SKIN AND BROKEN STRINGERS FROM STRINGERS 44LITO 49 RIGHT. BEGINNING AT STA 1920 THE TEAR BEGINS AT STR 44L AND RUNS DOWN TO STR 48L. THE TEAR CONTINUES THROUGH STRS 49L AND 50L TO STATION 1960, THEN DOWN UNDER THE FUSELAGE TO STR 49R WHERE IT RUNS TO STA 2020 AND CONTINUES UP TO STR 45L. A JAGGERED PATTERN RUNNING BETWEEN STRS 44L \$45L THEN CONTINUES FORWARD TO STATION 1920.

MOST STATION FORMERS ARE MISSING. STR 51L, 50L \$49L. ARE BROKEN OUTWARD. THE COMPLETE SECTION 15 CRUMPLED AND BROKEN FROM IMPACT.

THERE IS NO EVIDENCE OF FIRE OR HEAT DAMAGE.

REFER FIRE AND EXPLOSION GROUP NOTES FOR FIRE DAMAGE

•

