

Promech Air LLC
Ketchikan, Alaska
June 25, 2015
ANC15MA041

**NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C.**

ATTACHMENT 1

PHOTOGRAPHS OF EXEMPLAR AIRPLANE

Pages 5

A. Photographs of Exemplar Airplane

Promech Air, LLC was conducting routine maintenance on an airplane similar to the accident airplane. The group visited their facility on August 18, 2015. The following are photographs taken from the exemplar airplane.



Photograph 1- Photograph of interior cabin standing at the cockpit looking aft.



Photograph 2- Photograph of R3, R4, and R5 seat and right side cabin door.



Photograph 3- Photograph of interior cabin standing aft looking forward toward the cockpit. R4 seat bent forward. Headsets stowed.



Photograph 4- Photograph of stowed seats R5 and L5 and cargo stowage.



Photograph 5- Photograph of L5 seat.



Photograph 6- Photograph of R4 seat forward of right side cabin door.



Photograph 7- Photograph of right side cabin interior seats standing forward looking aft toward cargo stowage.



Photograph 8- Photograph of stowed cabin interior seat.



Photograph 9- Photograph of stowed cabin interior seat with wired cable.



Photograph 10- Photograph of stowed cabin interior seat and a cabin interior seat in its downward and locked position.