

Delta Air Lines  
LaGuardia Airport- Queens, New York  
March 5, 2015  
DCA15FA085

**NATIONAL TRANSPORTATION SAFETY BOARD  
WASHINGTON, D.C.**

ATTACHMENT 12

PASSENGER PHOTOGRAPHS

Pages 6



**PHOTOGRAPH 1 – Photograph looking out of the left side window at the left wing over Flushing Bay.**



**PHOTOGRAPH 2 – Photograph looking out of the left side window at the 500 foot runway marker.**



**PHOTOGRAPH 3 - Photograph looking out of left side window at the left wing inside a mangled fence.**





**PHOTOGRAPH 4 - Photograph looking out of left side window at the tailcone slide.**



**PHOTOGRAPH 5 - Passengers are on tarmac in the snow. A fire truck are positioned aft of aircraft. Two firefighters are on the right side wing helping passengers out of aircraft.**