Gulfstream Aerospace Roswell, NM April 2, 2011 DCA011MA076

## NATIONAL TRANSPORATION SAFETY BOARD WASHINGTON, D.C.

## ATTACHMENT 14

## ON-SITE ACCIDENT PHOTOGRAPHS WITH TIMESTAMPS

(with 11 embedded photographs)

6 Pages



Photograph 1: Time of photograph was 15:34:15 UTC.



Photograph 2: Time of photograph was 15:37:22 UTC.




Photograph 3: Time of photograph was 15:38:17 UTC.



Photograph 4: Time of photograph was 15:38:19 UTC.



Photograph 5: Time of photograph was 15:38:35 UTC.



Photograph 6: Time of photograph was 15:38:41 UTC.




Photograph 7: Time of photograph was 15:38:59 UTC.



Photograph 8: Time of photograph was 15:39:04 UTC.



Photograph 9: Time of photograph was 15:39:52 UTC.



Photograph 10: Time of photograph was 15:49:26 UTC.



Photograph 11: Time of photograph was 15:53:06 UTC.