Gulfstream G-150, N480JJ Key West, Florida October 31, 2011 ERA12FA056

National Transportation Safety Board Washington, D.C.

## Attachment 2

Gulfstream Installation Log Book Excerpt Excerpts Work Order (WO) No. SC188828 Excerpts WO# SC228125

3 Pages

REMOVAL INSTALLATION LOC 300K														
		JOB NO:					AIRCF	AFT SERI		pace Corp	J. DAL			V3 1K300K
PART NUMBER	SERIAL NUMBER	MANUFACTURER MFG Part Number	CMP CODE	MAINT REF	TSO NUMBER	DATE	K TO REMO MECH				QC			CERT P INSP
14 D. S. F. T. 14 P. 15			CAB	IN.										
OFF HEW	OFF New	B/E ALLO						17	15 PAU			1.5		
ON AL-2034-200-000	ON 321	V	wт	FS					383	45	4	038	1	
OFF Hew	New	3/E AERO						1/	15 37W	1/	110	DAN		X5
ON AL-2034-200 -000	ON 323		Wτ	FS	ļ	/_		/_	08 3		4	055		
OFF WEW	OFF WEW	CAC							1/15/08 1	1	7	15/03 KE		) [
ON GAZZZZYWOO	A/CA NO		WT29.5	FS	-		//		, , , ,	1	1	5	4	4
OFF WEW	DEW_	GAC	<u> </u>	<u> </u>	4		1/		15/08		VK	15/A KE	1/	
01 A322046000-17	ON AYA		WT 30.2	FS	<del> </del>	Y-,	<del>/                                    </del>	K	J. S	}-	37	11	e l	<del> </del>
NEW	WEW_	GAC		-	4				25/	1		25/02/0		
GA322010000-15	N/A		WT. 24,65	FS	+	/	K-	<del>/ /</del>	1.	4	-1	1 1		1
NEW	new	GAC	101		-				125/03		;/\\	25/03/19	2	到)
	OFF N/A	1000	WT10-10	FS		/	1	<del>- / /</del>	11	+	4.	11 1	toy.	
( way)	ON , 3 ( -0	AMP	120		-			1118/4	1	1/18/8/8				
IOCC	OFF Mas	A 100 D	WTOZIS	FS	<del> </del> -		1		11 )		-1,	7 7 1	1	<u> </u>
	ON	J CF MY	1339	FC	-				18/0	1	t.	118/08	3	7
Marie Control of the		1 amp	W1471	FS	+	1	1	1	11 1.	nt		1171	#	
ON	ON 11	177	WT 1279	EC	•				18/8/	9	4.00	1/18/4		)
TOES	OFF ILLUST	I D M D	WI COCK /	153	+		1	1	117 1	- 1	1170		s l	
ON OF SOLOW THE	Manager and American American	1 19 19 1	WT 23.5	FS				418/0	1	+	418/8 4	4	*	
		amp	1		<b></b>		1		1.1	7		17		
		1-10-10-10-10-10-10-10-10-10-10-10-10-10	w163,9	FS					1186			1/5/88	9	1 (d)
OFF	OFF	Ama				17	1	/	11/1			1171	03	~
ON FERIOL (OVA)			WT(13:6	FS					/18/8		( · · ·	118/8 g	i	
	PART NUMBER  OFF NEW ON 2034-200-000 OFF NEW ON 2432201000-15 OFF NEW ON 25201000-15 OFF NEW ON 252010000-15 OFF NEW ON 25201000-15 OFF NEW ON 25201	PART NUMBER  SERIAL NUMBER  OFF NEW OFF NEW  ON AL 2034-200-000 ON 321  OFF NEW OFF NEW  ON ABZZZZYLOZO-17 ON N/A  OFF NEW OFF NEW  ON ABZZZZYLOZO-11 ON N/A  OFF NEW  ON ABZZZZYLOZO-11 ON N/A  OFF NEW  ON ABZZZYLOZO-11 ON N/A  OFF NEW  ON ABZZZZYLOZO-11 ON N/A  OFF NEW  ON ABZZZZYLOZO-11 ON N/A  OFF NEW  ON OFF NEW  ON ON 11  OFF NEW  ON ON 128-04	DOB NO: FP4922  PART NUMBER  SERIAL NUMBER  MANUFACTURER MFG PART Number  MFG PART Number	PART NUMBER  SERIAL NUMBER  MANUFACTURER CMP CODE MFG PART Number  WEIGHT:  CAB  OFF NEW OFF N	JOB NO: Gulfstream 15  PART NUMBER SERIAL NUMBER MANUFACTURER CMP CODE MAINT REF MEG PART Number WEIGHT & BALANCE  CABIN  OFF New OFF New SIL ALLO  OFF New OFF New SIL ALLO  OFF New	DISCRIPTION OF SERIAL NUMBER  PART NUMBER  SERIAL NUMBER  MANUFACTURER MFG PART NUMBER  MANUFACTURER MFG PART NUMBER  MANUFACTURER MFG PART NUMBER  CABIN  CABIN  OFF NEW OFF	DOR NO: FP4922  PART NUMBER  SERIAL NUMBER  MANUFACTURER CAMPODDE MAINT REF  WEIGHT & BALANGE  NUMBER  OFF  NEW	DOE NO: FP4922  PART NUMBER  SERIAL NUMBER  MANUFACTURER MFG PAIR Number  WEIGHT & BALANCE  NUMBER  OFF  NEW  OFF  OFF  NEW  OFF  NEW  OFF  NEW  OFF  NEW  OFF  NEW  OFF  NEW  OFF  OFF  NEW  OFF  NEW  OFF  OFF  OFF  OFF  OFF  OFF  OFF  O	DOB NO: GREAT MODEL NO: ARCRAFT MODEL NO: ARCRAFT SERVING FRANCE  PART NUMBER  SERIAL NUMBER  MANUFACTURER CAP CODE  MAINT REF  SO  OK TO REMOVE  MEGH T NUMBER  CABIN  OK TO REMOVE  ALL  OK A	SCHISTORY ARGRAFT MODEL NO:  PART NUMBER  SERIAL NUMBER  SERIAL NUMBER  MEG PART NUMBER  SERIAL NUMBER  MEG PART NUMBER  MEG	SERIAL NUMBER    PART NUMBER NUMBER   PART NUMBER   PART NUMBER NUMBER NUMBER   PART NUMBER NUMBER NUMBER   PART NUMBER NUMBER NUMBER   PART NUMBER N	PART NUMBER  SERIAL NUMBER  SERIAL NUMBER  SERIAL NUMBER  SERIAL SUMMER  MANUFACTURER  COMP CODE MANTER THE TISO  OK TO RENOVE  OK TO RENOVE	PART NUMBER   SERIAL NUMBER   MANUFACTURER   MEG PAR Number   MEG PAR Nu	DIS NO: SERIAL NUMBER  SERIAL NUMBER  SERIAL NUMBER  SERIAL NUMBER  MANUFACTURER  MANU

Bill To: H	ENDRICK MO	TORSPORTS	WO #: SC188828	Invoice Number: 5509117788
Step:	5.8.1	Completed	Interior Support complied with, see steps below for work	performed.
Step:	5.8.1.1	Completed	Removed the following items for mech access: The R/H #1 071128-014, The L/H #1 seat P/N 3AEF0101(010) S/N 071 3AEF0101(029) S/N 071128-03, The L/H #2 seat P/N 3AEI The R/H #3 seat 3AEF0101(042) S/N 071128-06 and the L 3AEF0101(041) S/N 071128-05. All work was performed p	128-02, The R/H #2 seat P/N F0101(030) S/N 071128-04, /H #3 seat P/N
Step:	5.8.1.2	Completed	Received the ok to install and installed the following items 3AEF0101(009) S/N 071128-014, The L/H #1 seat P/N 3AEF0101(029) S/N 071128-03, The 3AEF0101(030) S/N 071128-04, The R/H #3 seat 3AEF010 L/H #3 seat P/N 3AEF0101(041) S/N 071128-05. All work CCMH 25-21-00.	i: The R/H #1 seat P/N EF0101(010) S/N 071128-02, <mark>L/H #2 seat P/N</mark> I1(042) S/N 071128-06 and the
Step:	5.8.1.2.1	Completed	Received the ok to install and installed the following items 3AEF0101(010) S/N 071128-02, The R/H #2 seat P/N 3AEI The L/H #2 seat P/N 3AEF0101(030) S/N 071128-04, The L/H #2 seat P/N 3AEF0101(030) S/N 071128-06 and the L/H #3 seat P/N 3AEF0101(041) S/seats to 35 inch pounds using torque wrench 558103 calibrates performed per the CCMH 25-21-00.	F0101(029) S/N 071128-03, R/H #3 seat 3AEF0101(042) N 071128-05 and torqured
Step:	5.8.1.3	Completed	Removed the following items for mech access: The vestibut carpet, The L/H carpet and the R/H carpet.	le carpet, The cabin center
Step:	5.8.1.4	Completed	Received ok to install and installed the vestibule carpet, T	
Step:	5.8.1.4.1	Completed	L/H carpet and the R/H carpet. All work was performed p Received the ok to install and installed the following items carpet. All work was performed per the CCMH 25-27-01.	
Step:	5.8.1.5	Completed	Removed the following items for mech access: The L/H aft header assembly, The aft lav pocket doors(2) and the aft law work was performed per the CCMH 25-23-00.	
Step:	5.8.1.6	Completed	Received ok to install and installed he L/H aft cover bulkh assembly, The aft lav pocket doors(2) and the aft lav toilet was performed per the CCMH 25-23-00.	
Step:	5.8.1.6.1	Completed	Received ok to install and installed L/H aft cover bulkhead backrest. Work performed per. GAMPS 2220 Rev.D.	l and aft lav toilet padded
Step:	5.8.1.7	Completed	Removed the following items for mech access: The upper headliner, The headliner brackets, The PSU, The upper variety downwash light lens and the upper vanit per the CCMH 25-40-02 and 25-27-15.	nity light upper light lens,
Step:	5.8.1.8	Completed	REINSTALLED: The upper headliner, The lower headline The PSU, The upper vanity light upper light lens, The upp	er vanity downwash light lens
Step:	5.8.1.8.1	Completed	and the upper vanity. All work was performed per. GAMF Received the ok to install and installed the upper vanity. A the CCMH 25-40-02 and 25-27-15.	S 2220 Rev.D. Il work was performed per
Step:	5.8.1.9	Completed	Removed the following items for mech access: The lav toile seat, The lav toilet ABS/subpanel, The lav toilet front shrot subpanel and the lav lower vanity. All work was performed	d, The lay toilet backrest
Step:	5.8.1.10	Completed	Received ok to install and installed lav toilet padded seat, I toilet ABS/subpanel, The lav toilet front shroud, The lav to lav lower vanity. All work was performed per GAMPS 222	he lav toilet seat, The lav ilet backrest subpanel and the
Step:	5.8.1.10.1	Completed	Received the ok to install and installed the following items: toilet ABS/subpanel, The lav toilet front shroud, The lav to lav lower vanity. All work was performed per the CCMH 2	ilet backrest subpanel and the
Step:	5.8.1.11	Completed	Removed the following items for mech access: The aft close inboard closeout, The aft closet shell, The aft closet bottom holder and the aft lav water tank. All work was performed 25-22-05.	t fwd bulhead, The aft closet closeout, The aft lav towel
Step:	5.8.1.12	Completed	Removed the L/H heater duct for mech access. All work wa 21-23-05.	
Step:	5.8.1.13	Completed	Recieved the ok to install and isntalled the L/H heater duct was performed per the CCMH 21-23-05.	for mech access. All work
Step:	5.8.1.14	Completed	Received ok to install and installed aft closet fwd bulhead, closeout, The aft closet shell, The aft closet bottom closeout	. The aft lay towel holder and
Step:	5.8.1.14.1	Completed	the aft lav water tank. All work was performed per GAMP. Received the ok to install and installed the following items: The aft closet inboard closeout, The aft closet shell and the work was performed per the CCMH 25-40-02 and 25-22-05	The aft closet fwd bulhead, aft closet bottom closeout, All
Step:	5.8.1.15	Completed	Received ok to install and installed L/H #1,2,3 and R/H #2,3 performed per. GAMPS 2220 Rev.D.	

For detail description of the work complied with see the Work Order Detail report.

Bill To: HENDRICK MOTORSPORTS	WO #: SC228125 Invoice Number: 5510128594
Step: 5.1.1 Completed	Interior Support.Complied with interior removeals and installs. See steps below for
Step: 5.1.1.1 Completed	work performed. Removed the following items: MED Threshold MED FWDSpring Cover MED AFT Spring Cover Vestibule Carpet Center Cabin Carpet 2 Boxes Customer Property Galley Header L/H Closet Shelves (3) Accoustical Curtain and Track L/H FWD Closet Drawer Cock-pit Curtain and Track Cock-pit Header Entry Headbumper Vestibule Headliner L/H FWD Closet L/H PSU (Lowered) R/H PSU (Lowered) Cabin Headliner
Step: 5.1.1.2 Completed	Removed the following seats:  L/H # 1 Seat: S/N 071128-02  R/H # 1 Seat: S/N 071128-01  R/H # 2 Seat: S/N 071128-03  R/H # 3 Seat: S/N 071128-06  P/N 3AEF0101- (009)  P/N 3AEF0101- (029)  P/N 3AEF0101- (042)
Step: 5.1.1.3 Completed	To Be Installed:  1./H # 1 Seat: S/N 071128-02 P/N 3AEF0101- (010)  R/H # 1 Seat: S/N 071128-01 P/N 3AEF0101- (009)  R/H # 2 Seat: S/N 071128-03 P/N 3AEF0101- (029)  R/H # 3 Seat: S/N 071128-06 P/N 3AEF0101- (042)
Step: 5.1.1.4 Completed	To Be Installed: MED Threshold MED FWDSpring Cover MED AFT Spring Cover Vestibule Carpet Center Cabin Carpet 2 Boxes Customer Property Galley Header L/H Closet Shelves (3) Accoustical Curtain and Track L/H FWD Closet Drawer Cock-pit Curtain and Track Cock-pit Header Entry Headbumper Vestibule Headliner L/H FWD Closet L/H PSU (Lowered) R/H PSU (Lowered) Cabin Headliner
Step: 5.1.1.5 Completed	Removed the Following: Aft Lav Life Raft storage box Aft Lav lower Storage shelf Customer property (1 box)
Step: 5.1.1.6 Completed	To Be Installed: Aft Lav Life Raft storage box Aft Lav lower Storage shelf Customer property (1 box)
Step: 5.1.1.7 Completed	Recieved ok to install and installed, Cabin headliner, Galley header, vestabule headliner,  I/h fwd closet, I/h fwd closet shelves (3),I/h and r/h psu, I/h fwd closet drawer, headbumper,lav closet bottom shelf.Work performed per CCMH  25-22-02,25-22-05,25-27-10,25-34-00.

For detail description of the work complied with see the Work Order Detail report.