



The right side of the SUV is shown. The vehicle is badly fire damaged and the middle portion of the car between the wheels is crushed inward. The fire damage is slightly less severe at the front, with the right front tire and wheel intact, but the tire is deflated. The right rear tire is burned away and the wheel is discolored. At the top left corner of the wheel there is a section of railroad rail visible, protruding from the side of the car.