



Systems 9 - 747-SL-20-048 - Fig. 8. A wing-body pressure seal penetration in good condition. Inspections should ensure the seals have not been compromised.