

COMPENSATOR (45)



Systems 9 - Exhibit No. 9B - Photo 1. Figure 1g.
Sample 45 from N93110 center tank. Typical damage to
recovered compensator.