

The contact material.




Figure 12. EDS spectrum of a area described as being tarnished on the stationary line contact of the SPR circuit breaker. The silver in both spectrums is primarily from the

Systems 9 - Exhibit No. 9B - Photo 12. Figure 12c. EDS spectrum of an area described as being tarnished on the stationary line contact of the SPR circuit breaker. The silver in both spectrums is primarily from the contact material.