



Systems 9 - Exhibit No. 9B - Photo 15. Figure 15g-2. Elemental X-ray microanalysis of damaged Hi-Z shield pigtail lead wire from N93119, probe #52 (circled are, Figure 14).