

Systems 9 - Exhibit No. 9B - Photo 16. Figure 16c. The moving contacts of the RTV circuit breaker have a tarnished appearance. White arrows highlights mechanical wear from the making and breaking of the contacts. Black arrow indicates fibrous residue.