


SPECIMEN 59

Black deposits are most likely "soot" from burning fuel

PC 1 THERMAL DAMAGE

A photograph of a specimen, likely a piece of wood or a similar material, showing thermal damage. The specimen is light-colored with a dark, charred area on the left side. Two white arrows point to black deposits on the specimen, which are identified as soot from burning fuel. A ruler is visible at the bottom of the image, showing measurements in inches. The specimen is labeled 'SPECIMEN 59' and 'PC 1 THERMAL DAMAGE'. A caption below the image reads: 'Systems 9 - Exhibit No. 9B - Photo 16. Figure 16g. Black stain found to be soot from burning fuel (from N93119).'

Systems 9 - Exhibit No. 9B - Photo 16. Figure 16g. Black stain found to be soot from burning fuel (from N93119).