



Systems 9 - Exhibit No. 9B - Photo 2. Figure 2f. Typical example of hot stamp markings on relay connector wiring. Note depth penetration of the mark. A close-up of the seven mark is shown at the top. Mag