



Systems 9 - Exhibit No. 9B - Photo 2. Figure 2g. Sample 22 from N93119 center tank. Typical damage to recovered fuel probe.