



Systems 9 - Exhibit No. 9B - Photo 3. Figure 3d. Blackened and thermally damaged area on wiring. Note raised area (arrow).