



Systems 9 - Exhibit No. 9B - Photo 36. Figure 36g. Compensator (model no. FG6C1, serial no. 1-166) from N93105 having apparent compression damage to PTFE insulation.