

**The same compression
damage seen in Figure 36,
found to have exposed
conductor at several points
contact**



0.06 inch

Systems 9 - Exhibit No. 9B - Photo 37. Figure 37g. Compensator (model no. FG6C1, serial no. A-166) from N93105 having apparent compression damage to PTFE insulation.