



Systems 9 - Exhibit No. 9B - Photo 4. Figure 4b. Radiograph of relay. Arrow showing the N.C. contacts are open.