



Closer view of exposed conductor in circled area of Figure 48

0.06 inch

Systems 9 - Exhibit No. 9B - Photo 49. Figure 49g. Fuel probe (model no. FG420A12, serial no. A-9) from N93105 having apparent compression damage to PTFE insulation.