



Systems 9 - Exhibit No. 9B - Photo 5. Figure 5f. Cross section of the wire showing three layer construction and depth penetration of the hot stamp mark. Note thickness of layers and total thickness at bottom right. Note deformation in inner layer.