


**Closer view of circled area in figure 50 (damage to PTFE insulation from contact with smooth terminal block surface)**



**Exposed Conductor**

**0.06 inch**

**Systems 9 - Exhibit No. 9B - Photo 51. Figure 51g. Compensator (model no. FG6C1, serial no. A-166) from N93105 with compression damage to PTFE insulation.**