



Systems 9 - Exhibit No. 9B - Photo 6. Figure 6f. Perpendicular cross section showing depth penetration of the hot stamp marks. Note that all three insulation layers were penetrated and the inner white layer was deformed by the stamping process.