



Systems 9 - Exhibit No. 9B - Photo 6. Figure 6a. The environmental seal of the left jettison switch exhibiting corrosion and salt water-like deposits.