



Systems 9 - Exhibit No. 9B - Photo 7. Figure 7f. Lateral cross section showing multiple hot stamp sites. Note variability of depth penetration from right to left. Note close-up of upper left mark showing the mark penetrated all three insulation layers.