



Systems 9 - Exhibit No. 9B - Photo 8. Figure 8b. Residues on and surrounding the glass to metal seal of N.O. contact A1.