



Systems 9 - Exhibit No. 9B - Photo 9. Figure 9g. Insulation surrounding an internal fuel probe terminal. Part was removed from an unidentified fuel probe in the N93110 wreckage. Note darkened regions. X-ray maps of areas were rich in copper and sulfur.