



Systems 9 - Exhibit No. 9E - Photo No. 11 - CWT FQIS probe from left rear bay of N93105, showing red wire under clamp. ATA 28-41-01.