



Systems 9 - Exhibit No. 9B - Photo 4. Close-up view (looking forward) of left ground spoiler hinge (arrow). Note extensive heat and soot damage.