



Systems 9 - Fuel Quantity Indication System - Photo 12.
Drill shavings visible in sealant at bottom of STA 920
floorbeam. (Digital image)