



Systems 9 - Fuel Quantity Indication System - Photo 23.  
Debris from within VSO unit included plastic, metal, and  
sand. (No negative)