



Systems 9 - Fuel Quantity Indication System - Photo 9. Structure repairs from bottom of main deck cabin floor. Location is ahead of forward spar. Repairs are to left and right of the airplane centerline, which is marked "BL 0." Left edge of photo is forwa