



Systems 9 - Photo 11. Airplane 7. B-747 Floor structure repair in electrical equipment center, aft of station 400 (left side). Grouped open splices also visible in bundle.