



Systems 9 - Photo 11. View of E/E from the forward baggage compartment (looking forward). Note the nose gear folded back into the compartment clocked 90 degrees to the right. The left nose gear tire has been removed to gain access.