



Systems 9 - Photo 14. Airplane 8. DC-9-30 in electrical equipment center at top of left power distribution panel. Visible are drill shavings and rivet fragments. Mixture of wire types is visible. Location is covered by floor boards.