



Systems 9 - Photo 16. Airplane 9. B-747 Cockpit floor behind flight engineer panel. On and between wires are dirt, lint, and metal shavings. Mixed wire types visible. (View down & forward from near right escape door)