



Systems 9 - Photo 22. Airplane 11. B-747 wires forward of wing spar in left raceway. Arrows point to metal shavings on wire and coming through the bottom of the bundle. Deep hot stamp letters in wire insulation at lower left have ridged edges.