



Systems 9 - Photo 25. Airplane 12. B-747 in CWT, showing CWT FQIS wire chafe on structure.