



Systems 9 - Photo 27. Airplane 12. B-747 over forward cargo compartment with left side of the forward spar visible. The cargo compartment ceiling liner has been removed. (View is aft-right and forward is to right of