

Systems 9 - Photo 28. Airplane 13. Spanish Customs form found between generator cables in 747 and laid on insulation near STA 400. Around the form are metal shavings, loose hardware, rivet fragments, and dirt. Form is dated 5-17-96.