



Systems 9 - Photo 3. Airplane 3. Exposure of fuel quantity and fire system wire bundles in B-747-400 forward cargo compartment, beneath aft cargo motor. No covers have been removed. (View is down. Right edge is forward).