



Systems 9 - Photo 30. Airplane 13. B-747 station 400 (right) opening with clamp loosened for photo. Insulation of adjacent wire chafed off at nylon edge of clamp. Also visible are a mixture of new and old wire and drill shavings.